

ACURA P1077: INTAKE MANIFOLD TUNING (IMT) VALVE STUCK IN HIGH RPM POSITION

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Advanced
Repair Cost	:	\$100-\$2050
Can I Still Drive?	:	Yes

What Does The Acura P1077 Code Mean?

When the PCM sends a close (long runner) command, no long runner return signal is received for at least 7 seconds. Execution is once per drive cycle, engine speed, 3,600 rpm and intake air temperature a minimum of 5 °F (-15 °C).

NOTE: Before you troubleshoot, record all freeze data and any on-board snapshot.

What Are The Potential Causes Of The Acura P1077 Code?

- Poor connections or loose terminals at the IMT actuator and the PCM
- "Open" circuit between the PCM and the IMT actuator
- Faulty IMT actuator
- PCM may need to be updated with the latest software
- Faulty PCM

Reference Sources

[Acura P1077](#), DTCDECODE.