

ACURA P1106: MAP SENSOR CIRCUIT HIGH INPUT (INTERMITTENT)

OVERVIEW

Severity	:	<div>High</div>
DIY Difficulty Level	:	<div>Intermediate</div>
Repair Cost	:	\$100-\$300
Can I Still Drive?	:	Yes

What Does The Acura P1106 Code Mean?

DTC [P0121](#), [P0122](#), [P0123](#) not set, engine runtime 10 seconds, engine speed less than 1000 rpm with throttle angle less than 3%, or the engine speed is more than 1000 rpm with the throttle angle less than 10%, and the PCM detected an unexpected high value (o

What Are The Potential Causes Of The Acura P1106 Code?

- MAP sensor signal circuit is open (an intermittent fault)
- MAP sensor signal circuit is shorted to VREF (intermittent fault)
- MAP sensor is damaged or has failed

Reference Sources

[2001 Engine Performance Acura Self-Diagnostics](#), MDX, 3.2CL & 3.2TL, page 34.