

## ACURA P1129: MANIFOLD ABSOLUTE PRESSURE (MAP) SENSOR SIGNAL HIGHER THAN EXPECTED

### OVERVIEW

Severity	:	<div><div>High</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$100-\$300
Can I Still Drive?	:	Yes

### What Does The Acura P1129 Code Mean?

The MAP sensor output is 36 kPa (10.9 in. Hg, 277 mmHg) or more for at least 2 seconds. The execution time is once per driving cycle.

**NOTE:** Before you troubleshoot, record all freeze data and any on-board snapshot.

### What Are The Potential Causes Of The Acura P1129 Code?

- Vacuum leaks
- Poor connections or loose terminals at the MAP sensor and the PCM
- Faulty MAP sensor

### Reference Sources

[2001 Engine Performance Acura Self-Diagnostics](#), MDX, 3.2CL & 3.2TL, page 35.