

ACURA P1696: TCFC DATA LINE SIGNAL LOW INPUT

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$75-\$200
Can I Still Drive?	:	Yes (Short-term only)

What Does The Acura P1696 Code Mean?

This code indicates the condition that key on or engine running; and the PCM detected an unexpected "low" input on the TCFC Data Line circuit during the CCM test.

Note: This code applies to models with a Traction Control System.

What Are The Potential Causes Of The Acura P1696 Code?

Below are some potential causes of this DTC:

- A/T TCFC data line is shorted to sensor ground
- A/T TCFC data line is shorted to chassis ground
- TCM or PCM has failed

Reference Sources

[Acura P1696](#), DTCDECODE.