BMW P1077: VALVETRONIC (VVT) OVERLOAD PROTECTION CONTROL MOTOR TEMPERATURE HIGH INPUT (BANK 1)

OVERVIEW

Severity : Medium

DIY Difficulty Level : Intermediate

Repair Cost : \$300-\$500

Can I Still Drive? : Yes (Short-term only)

What Does The BMW P1077 Code Mean?

This code indicates that after the ignition is on for 45ms, the E motor temperature was recorded as too high.

What Are The Potential Causes Of The BMW P1077 Code?

Below are some potential causes of this DTC:

- Sticking in VVT mechanicals, pinion gear, etc.
- Loose sensor
- Sensor servo motor has short circuit

Reference Sources

BMW P1077, DTCDECODE.

