

CHEVROLET P1484: COOLING FAN SPEED EXCESSIVE RPM

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$100-\$300
Can I Still Drive?	:	Yes (Short-term only)

What Does The Chevrolet P1484 Code Mean?

The engine is running. The system voltage is greater than 8.5 volts. The intake air temperature (IAT) is greater than -7°C (19°F). DTCs P1481 and P1482 are not set. The engine speed is less than 3200 RPM.

What Are The Potential Causes Of The Chevrolet P1484 Code?

An inline connector could cause an intermittent DTC. Ensure to test for poor connections and pin retention at all inline connectors. Refer to system schematics for connector and locations.

Reference Sources

[Chevrolet P1484](#), DTCDECODE.