

## What Does The Chevrolet P1509 Code Mean?

Engine started, engine runtime over 2 minutes, ECT sensor more than 132°F, IAT sensor more than 68°F, vehicle speed less than 3 mph with the throttle closed, and the PCM detected the Actual idle speed was 175 rpm higher than the Desired idle speed.

## What Are The Potential Causes Of The Chevrolet P1509 Code?

- Base engine problem (engine vacuum leak or PCV valve leak)
- IAC motor is damaged or has failed (it may be sticking)
- IAC motor circuit open, shorted to ground or shorted to power
- Throttle body adjustment screw tampered with or damaged

## **Reference Sources**

GM, 2013, Service Bullettin - Prior To Any Circuit Testing.

