

P0159: OXYGEN SENSOR CIRCUIT SLOW RESPONSE (BANK2, SENSOR2)



OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$100-\$300
Can I Still Drive?	:	Yes (Short-term only)

What Does The P0159 Code Mean?

This involves the rear oxygen sensor on the passenger side. Bank 2 is the side of the engine that does not contain cylinder #1. Sensor #2 is the second sensor downstream from the engine.

This code indicates the engine air fuel ratio is not being adjusted by the oxygen sensor signal or the ECM as expected to do so, or not adjusted as often as expected to do so once the engine is warmed or under normal engine use.



P0159 wiring diagram

What Are The Symptoms Of The P0159 Code?

You will likely not notice any drivability problems, although there may be symptoms.

What Are The Potential Causes Of The P0159 Code?

A code P0159 may mean that one or more of the following has happened:

- The oxygen sensor is faulty
- The wiring to the sensor is broken / frayed
- There is an exhaust leak

How Can You Fix The P0159 Code?

The simplest thing to do is to reset the code and see if it comes back.

If the code comes back, the problem is more than likely the rear passenger side oxygen sensor. You will likely wind up replacing it but you should also consider these possible solutions:

- Check and fix any exhaust leaks
- Check for wiring problems (shorted, frayed wires)
- Check the frequency and amplitude of the oxygen sensor (advanced)
- Check for a deteriorating / contaminated oxygen sensor, replace if necessary
- Check for inlet air leaks
- Check the MAF sensor for proper operation

Reference Sources

[ENGINE CONTROL SYSTEM \[GASOLINE ENGINE \(V-6\)\] SERVICE MANUAL for P0159](#) - Pages 447-453.