

What Does The Volkswagen P1655 Code Mean?

The Engine Control Module (ECM) communicates with all databus-capable control modules via a CAN databus. These databus-capable control modules are connected via two data bus wires which are twisted together (CAN_High and CAN_Low), and exchange information.

What Are The Potential Causes Of The Volkswagen P1655 Code?

- Ground between engine and chassis may be broken
- Throttle position sensor may have failed
- Accelerator Pedal Position Sensor 2 has failed
- Throttle position sensor wiring may have shorted
- Faulty voltage supply
- ECM has failed

Reference Sources

Volkswagen P1655, DTCDECODE.

