ACURA B1000: COMMUNICATION BUS LINE ERROR	
	OVERVIEW
:	Medium
:	Intermediate
:	\$90-\$150
:	Yes (Short-term only)
	:

What Does The Acura B1000 Code Mean?

This code indicates failure from the communication bus line.

Note: DTCs <u>B1005</u>, <u>B1007</u>, <u>B1011</u>, <u>B1012</u>, <u>B1013</u>, <u>B1015</u> and <u>B1032</u> may all be indicated.

What Are The Potential Causes Of The Acura B1000 Code?

Below are some possible causes of this DTC:

- Intermittent failure in the communication bus line. Check for loose or poor connections, or worn/shorted wires
- Poor battery condition and/or charging system
- Short to power in B-CAN wire
- Faulty MICU, replace the under-dash fuse/relay box

Reference Sources

<u>Accessories & Equipment Multiplex Integrated Control System Service Manual for B1000</u> - 2004 Acura TSX, pages 38-39.

