

Acura B1007: MICU Lost Communication with Combination Switch Control Unit (HLSW Message)

OVERVIEW

Severity

:

Medium

DIY Difficulty Level

:

Intermediate

Repair Cost

:

\$75-\$200

Can I Still Drive?

:

Yes

What Does The Acura B1007 Code Mean?

Poor communication between the MICU and the Combination Switch Control Unit. Inoperative or intermittent Headlamp Switch.

What Are The Potential Causes Of The Acura B1007 Code?

- Loose or poor connections between the MICU and the Combination Switch Control Unit.
- Blown fuse in the main under-hood fuse box
- Blown fuse in the under-dash fuse/relay box
- Faulty MICU
- Faulty Headlamp Switch (Combination Switch Control Unit).

Reference Sources

[Accessories & Equipment Multiplex Integrated Control System Service Manual for B1007](#) - 2004

Acura TSX, pages 41-42.