

ACURA B1012: MICU LOST COMMUNICATION WITH REAR MICU (RJC MESSAGE)

OVERVIEW

| | | |
|----------------------|---|------------------------------------|
| Severity | : | <div><div>Medium</div></div> |
| DIY Difficulty Level | : | <div><div>Intermediate</div></div> |
| Repair Cost | : | \$75-\$200 |
| Can I Still Drive? | : | Yes |

What Does The Acura B1012 Code Mean?

Poor Communication with Rear MICU

What Are The Potential Causes Of The Acura B1012 Code?

- If DTC B1955 is indicated with DTC B1012 suspect Rear MICU input malfunction.
- Blown No. 4 (40 A) fuse in the main under-hood fuse box
- Blown No. 6 (7.5 A) fuse in the under-dash fuse/relay box
- Rear MICU terminals are bent, loose or corroded
- "Open" or "Short to Ground" at the Rear MICU
- "Open" or "Short to Ground" at the Under-dash MICU
- Faulty Rear MICU
- Faulty Under-dash MICU

Reference Sources

[Acura B1012](#), DTCDECODE.