

ACURA B1052: RELAY CONTROL MODULE INTERNAL (EEPROM) ERROR

OVERVIEW

Severity	:	<div style="display: inline-block; width: 100%;"><div style="width: 50%; background-color: #e69d00; color: white; text-align: center; padding: 2px;">Medium</div></div>
DIY Difficulty Level	:	<div style="display: inline-block; width: 100%;"><div style="width: 50%; background-color: #e69d00; color: white; text-align: center; padding: 2px;">Intermediate</div></div>
Repair Cost	:	\$50-\$250
Can I Still Drive?	:	Yes (Short-term only)

What Does The Acura B1052 Code Mean?

This code indicates an internal failure from the Relay Control Module.

What Are The Potential Causes Of The Acura B1052 Code?

Main cause: Faulty relay control module.

Replace the under-hood fuse/relay box to solve this code.

Reference Sources

[Acura B1052](#), DTCDECODE.