| ACURA B1178: F-CAN COMMUNICATION LINE ERROI |   |            |        |          |
|---|---|------------|--------|----------|
|   |   | OVERVIEW   |        |          |
|   |   |            |        |          |
| Severity                                    | : |            | Medium |          |
| DIY Difficulty Level                        | : |            |        | Advanced |
| Repair Cost                                 | : | \$80-\$400 |        |          |
|   |   |            |        |          |

## What Does The Acura B1178 Code Mean?

Poor communication on the (F-Can) Fast controller Area Network line.

## What Are The Potential Causes Of The Acura B1178 Code?

- Check for Fuel and Emissions Systems DTCs first, then retest
- Loose or poor connection between the Gauge Control Module and the PCM
- "Open" or "Short" between Gauge Control Module and the PCM
- Update the PCM if it does not have the latest software
- Faulty Gauge Control Module
- Faulty PCM

## **Reference Sources**

<u>Accessories & Equipment Multiplex Integrated Control System Service Manual for B1178</u> - 2004 Acura TSX, pages 43-44.

