

ACURA B1213: AN OPEN IN THE REAR EVAPORATOR TEMPERATURE SENSOR CIRCUIT

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$250-\$350
Can I Still Drive?	:	Yes

What Does The Acura B1213 Code Mean?

Poor communication between the Rear Evaporator Temperature Sensor and the Climate Control Unit.

What Are The Potential Causes Of The Acura B1213 Code?

- Loose wires or poor connections on the rear evaporator temperature sensor circuit
- "Open" in the wire between the Climate Control Unit and the rear evaporator temperature sensor
- Faulty Rear Evaporator Temperature Sensor
- Faulty Climate Control Unit

Reference Sources

[2007-2009 Acura MDX HVAC Climate Control Service Manual for B1213](#) - Pages 36-38.