# ACURA B1246: PROBLEM IN THE REAR AIR MIX CONTROL LINKAGE, DOOR, OR MOTOR CIRCUIT

#### **OVERVIEW**

Severity : Medium

DIY Difficulty Level : Intermediate

**Repair Cost** : \$90-\$150

Can I Still Drive? : Yes

#### What Does The Acura B1246 Code Mean?

Poor communication between the Outside Air Temperature Sensor and the Climate Control Unit ("Open") condition.

## What Are The Potential Causes Of The Acura B1246 Code?

- Loose wires or poor connections on the Rear Air Mix Control Motor circuit
- Perform the HVAC self-diagnostic function with the HDS
- Blown fuse in the main under-hood fuse box
- Blown fuse in the under-dash fuse/relay box
- "Open" in the wire(s) between the Climate Control Unit and the Rear Air Mix Control Motor
- Broken linkage or door
- Faulty Rear Air Mix Control Motor
- Faulty Climate Control Unit

### **Reference Sources**

2007-2009 Acura MDX HVAC Climate Control Service Manual for B1246 - Pages 97-99.

