

ACURA B1378: POWER TAILGATE RIGHT PINCH SENSOR CIRCUIT MALFUNCTION

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$200-\$350
Can I Still Drive?	:	Yes

What Does The Acura B1378 Code Mean?

Poor communication between the Power Tailgate Right Pinch Sensor and the Power Tailgate Control Unit

What Are The Potential Causes Of The Acura B1378 Code?

- Loose or poor connections between the power tailgate control unit and the power tailgate right pinch sensor
- "Open" or "Short" between the Power Tailgate Right Pinch Sensor and the Power Tailgate Control Unit
- Faulty Power Tailgate Control Unit
- Faulty Power Tailgate Right Pinch Sensor

Reference Sources

[POWER TAILGATE TROUBLESHOOTING for B1378](#) - Pages 7-11.