

ACURA B1379: POWER TAILGATE LEFT PINCH SENSOR CIRCUIT MALFUNCTION

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$200-\$350
Can I Still Drive?	:	Yes

What Does The Acura B1379 Code Mean?

Poor communication between the Power Tailgate Control Unit and the Power Tailgate Left Pinch Sensor

What Are The Potential Causes Of The Acura B1379 Code?

- Loose or poor connections between the Power Tailgate Control Unit and the Power Tailgate Left Pinch Sensor
- "Open" or "Short" between the Power Tailgate Left Pinch Sensor and the Power Tailgate Control Unit
- Power Tailgate Left Pinch Sensor
- Power Tailgate Control Unit

Reference Sources

[POWER TAILGATE TROUBLESHOOTING for B1379](#) - Pages 11-16.