

ACURA B1806: POWER SEAT CONTROL UNIT LOST COMMUNICATION WITH MICU (MICU MESSAGE)

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$75-\$200
Can I Still Drive?	:	Yes (Short-term only)

What Does The Acura B1806 Code Mean?

This code indicates poor communication between the Power Seat Control Unit and the MICU.

NOTE:

- If you are troubleshooting multiple DTCs, be sure to follow the instructions in B-CAN System Diagnosis Test Mode A.
- If DTCs [B1055](#), [B1057](#), [B1157](#), [B1159](#), [B1255](#), [B1355](#), [B1955](#), B2155, B2156, and B2161 are also indicated, perform the MICU input test.
- If no additional codes are present. perform the Power Seat Control Unit input test.

What Are The Potential Causes Of The Acura B1806 Code?

Below are some possible causes of this DTC:

- Loose or poor connection between the Power Seat Control Unit and the MICU
- Blown fuse in the main under-hood fuse box
- Blown fuse in the under-dash fuse/relay box
- "Open" circuit between the Power Seat Control Unit and the MICU
- Poor ground
- Faulty Power Seat Control Unit

- Faulty MICU, replace the under-dash fuse/relay box

Reference Sources

[Acura B1806](#), DTCDECODE.