

Acura B1810: Power Seat Control Unit Lost Communication with MICU (MIRRORSW Message)

OVERVIEW

Severity

:

Medium

DIY Difficulty Level

:

Intermediate

Repair Cost

:

\$75-\$200

Can I Still Drive?

:

Yes

What Does The Acura B1810 Code Mean?

Poor communication between the Power Seat Control Unit and the Gauge Control Module.

NOTE: If you are troubleshooting multiple DTCs, be sure to follow the instructions in B-CAN System Diagnosis Test Mode A. If DTCs [B1011](#), [B1060](#), [B1061](#), [B1205](#), [B1357](#), [B1359](#), B1408, [B1805](#), [B1806](#), [B1906](#), and [B2160](#) are also indicated, Perform the gauge control module input test.

What Are The Potential Causes Of The Acura B1810 Code?

- Loose or poor connections between the Power Seat Control Unit and the Gauge Control Module
- Blown fuse in the main under-hood fuse box
- Blown fuse in the under-dash fuse/relay box
- "Open or "Short" Condition between the Power Seat Control Unit and the Gauge Control Module
- Faulty Mirror Switch
- Faulty Power Seat Control Unit
- Faulty Gauge Control Module

How Can You Fix The Acura B1810 Code?

If no addition codes are present, replace the Power Seat Control Unit.

Reference Sources

[Acura B1810](#), DTCDECODE.

