

ACURA B1825: POWER SEAT SLIDE MOTOR PULSE ERROR

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$75-\$200
Can I Still Drive?	:	Yes

What Does The Acura B1825 Code Mean?

Power Seat Slide Motor inoperative.

NOTE: If you are troubleshooting multiple DTCs, be sure to follow the instructions in B-CAN System Diagnosis Test Mode A.

What Are The Potential Causes Of The Acura B1825 Code?

- Loose or poor connections at the power seat control unit connector
- "Open" or "Short" in voltage circuit
- Faulty slide position sensor, replace the slide motor

Reference Sources

[Acura B1825](#), DTCDECODE.