ACURA B1828: POWER SEAT RECLINE MOTOR PULSE		
		ERROR
OVERVIEW		
_		
Severity	:	Medium
DIY Difficulty Level	:	Intermediate
•		
Repair Cost	:	\$200-\$300

What Does The Acura B1828 Code Mean?

Power Seat Recline Motor Malfunction.

NOTE: If you are troubleshooting multiple DTCs, be sure to follow the instructions in B-CAN System Diagnosis Test Mode A.

What Are The Potential Causes Of The Acura B1828 Code?

- Loose or poor connections at the Power Seat Control Unit connector
- "Open" or "Short" in the wire of the recline motor/lumbar support motor
- Faulty Recline Motor/Position Sensor
- Faulty Recline Motor
- Faulty Power Seat Control Unit

Reference Sources

Acura B1828, DTCDECODE.

