



ACURA B1829: A/T P SIGNAL AND VSS SIGNAL MISMATCH

OVERVIEW

Severity	:	 Medium
DIY Difficulty Level	:	 Intermediate
Repair Cost	:	\$75-\$200
Can I Still Drive?	:	Yes (Short-term only)

What Does The Acura B1829 Code Mean?

This code indicates A/T P Signal and VSS Signal Mismatch

NOTE: If you are troubleshooting multiple DTCs, be sure to follow the instructions in B-CAN System Diagnosis Test Mode A.

What Are The Potential Causes Of The Acura B1829 Code?

Below are some possible causes of this DTC:

- Loose or poor connections at the Power Seat Control Unit connector
- Troubleshoot the automatic transmission system
- Troubleshoot the Gauge Control Module
- Faulty Power Seat Control Unit

Reference Sources

[Acura B1829](#), DTCDECODE.