

ACURA B1835: POWER TILT/TELESCOPIC STEERING SWITCH SIGNAL INPUT ERROR

OVERVIEW

Severity	:	<div>High</div>
DIY Difficulty Level	:	<div>Intermediate</div>
Repair Cost	:	\$100-\$250
Can I Still Drive?	:	No

What Does The Acura B1835 Code Mean?

Power Tilt/Telescopic Steering Switch Signal Input malfunction.

NOTE: If you are troubleshooting multiple DTCs, be sure to follow the instructions in B-CAN System Diagnosis Test Mode A.

What Are The Potential Causes Of The Acura B1835 Code?

- Loose or poor connections at the tilt/telescopic switch connector and at the power tilt/telescopic control unit connector
- "Open" or "short" to ground
- Faulty Power Tilt/Telescopic Steering Switch
- Faulty Power Tilt/Telescopic Steering Control Unit

Reference Sources

[Acura B1835](#), DTCDECODE.