

ACURA B1843: POWER SEAT CONTROL UNIT LOST COMMUNICATION WITH POWER TILT/TELESCOPIC STEERING CONTROL UNIT (UART LINE)

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$75-\$200
Can I Still Drive?	:	No

What Does The Acura B1843 Code Mean?

Poor communication between Power Seat Control Unit and the Power Tilt/Telescopic Steering Control Unit.

NOTE: If you are troubleshooting multiple DTCs, be sure to follow the instructions in B-CAN System Diagnosis Test Mode A.

What Are The Potential Causes Of The Acura B1843 Code?

- Check for loose or poor connections
- Blown fuse in the main under-hood fuse box
- Blown fuse in the under-dash fuse/relay box
- "Open" condition between Power Seat Control Unit and the Power Tilt/Telescopic Steering Control Unit
- Faulty Power Seat Control Unit
- Faulty Power Tilt/Telescopic Control Unit

Reference Sources

[Acura B1843](#), DTCDECODE.