

ACURA B2178: FRONT PASSENGER'S POWER WINDOW MOTOR PULSE B ERROR

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Advanced
Repair Cost	:	\$250-\$510
Can I Still Drive?	:	Yes (Short-term only)

What Does The Acura B2178 Code Mean?

This code indicates Front Passenger's Power Window Motor malfunction.

NOTE: If you are troubleshooting multiple DTCs, be sure to follow the instructions in B-CAN System Diagnosis Test Mode A.

What Are The Potential Causes Of The Acura B2178 Code?

Below are some potential causes of this DTC:

- Check for loose or poor connections
- "Open" or "Short" Condition between the Front Passenger's Power Window Motor and the Front Passenger's MPCU Unit
- Faulty Front Passenger's Power Window Motor
- Faulty Front Passenger's MPCU Unit

Reference Sources

[Acura B2178](#), DTCDECODE.