

ACURA B2208: HANDSFREELINK CONTROL UNIT LOST COMMUNICATION WITH ACURALINK CONTROL UNIT

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$75-\$200
Can I Still Drive?	:	Yes (Short-term only)

What Does The Acura B2208 Code Mean?

This code indicates poor communication between HandsFreeLink Control Unit and the AcuraLink Control Unit.

What Are The Potential Causes Of The Acura B2208 Code?

Below are some potential causes of this DTC:

- Check the vehicle battery condition
- "Open" in the wire(s) between AcuraLink control unit (XM receiver) and the HandsFreeLink control unit.
- "Short" to body ground in the wire(s) between the AcuraLink control unit (XM receiver) and the HandsFreeLink control unit
- "Short" to power in the wire(s) between the AcuraLink control unit (XM receiver) and the HandsFreeLink control unit
- Faulty AcuraLink control unit (XM receiver)
- Update the AcuraLink control unit with the latest software
- Faulty HandsFreeLink Control unit

Reference Sources

[Acura B2208](#), DTCDECODE.