

## ACURA B2967: OPEN IN THE HUMIDITY SENSOR CIRCUIT (WINDSHIELD DEFROST)

### OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$100-\$250
Can I Still Drive?	:	Yes

### What Does The Acura B2967 Code Mean?

Climate Control malfunction

**NOTE:** Do the self-diagnostic function with the HDS or Climate Control Unit.

### What Are The Potential Causes Of The Acura B2967 Code?

- Loose wires or poor connections on the humidity sensor circuit
- Faulty Humidity/In-car Temperature Sensor
- "Open" in the wire(s) between the Climate Control Unit and the humidity sensor
- Faulty Climate Control Unit

### Reference Sources

[2007-2009 Acura MDX HVAC Climate Control Service Manual for B2967](#) - Pages 102-104.