ACURA B2968: SHORT IN THE HUMIDITY SENSOR CIRCUIT (WINDSHIELD DEFROST)

OVERVIEW

Severity : Medium

DIY Difficulty Level : Intermediate

Repair Cost : \$100-\$250

Can I Still Drive? : Yes (Short-term only)

What Does The Acura B2968 Code Mean?

This code indicates a short in the Humidity Sensor circuit.

Note: Do the self-diagnostic function with the HDS or climate control unit.

What Are The Potential Causes Of The Acura B2968 Code?

Below are some potential causes of this DTC:

- Loose wire or poor connection at Climate Control Unit
- "Short" to body ground
- "Short" to power in the wire. This short may have also damaged the climate control unit. Repair the short to power before replacing the climate control unit
- Faulty Climate Control Unit
- Faulty Driver's Air Mix Control Motor
- Faulty Passenger's Air Mix Control Motor
- Faulty Rear Air Mix Control Motor
- Faulty Humidity/In-car Temperature Sensor



Reference Sources

2007-2009 Acura MDX HVAC Climate Control Service Manual for B2968 - Pages 104-108.

