

## ACURA B2969: CLIMATE CONTROL UNIT LOST COMMUNICATION WITH COMBINATION SWITCH CONTROL UNIT (WIPSW MESSAGE)

### OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$75-\$200
Can I Still Drive?	:	Yes

### What Does The Acura B2969 Code Mean?

Poor communication between the Combination Switch Control Unit and the Climate Control Unit.

If any of the following DTCs are indicated; [B1958](#), [B1063](#), or [B1156](#), perform the wiper/washer switch (Combination Switch Control Unit) input test.

If no additional codes are present, perform the Climate Control Unit troubleshooting.

NOTE: If you are troubleshooting multiple DTCs, be sure to follow the instructions in the B-CAN system diagnosis test mode A.

### What Are The Potential Causes Of The Acura B2969 Code?

- Loose wire or poor connection on the climate control unit connector
- Blown fuse in the main under-hood fuse box
- Blown fuse in the under-dash fuse/relay box
- Poor ground

## Reference Sources

[2007-2009 Acura MDX HVAC Climate Control Service Manual for B2969](#) - Pages 108-109.