

ACURA B2976: SHORT IN THE DRIVER'S VENT AIR TEMPERATURE SENSOR CIRCUIT

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$100-\$300
Can I Still Drive?	:	Yes

What Does The Acura B2976 Code Mean?

Driver's Vent Air Temperature sensor ("Short") is indicated.

What Are The Potential Causes Of The Acura B2976 Code?

- Perform the climate control self-diagnostic with the HDS or the climate control unit.
- Loose wires or poor connections on the driver's vent air temperature sensor circuit
- "Short" to body ground in the wire between the climate control unit and the driver's vent air temperature sensor
- "Short" in the wires between the climate control unit and the driver's vent air temperature sensor
- Faulty driver's vent air temperature sensor
- Faulty climate control unit

Reference Sources

[Acura B2976](#), DTCDECODE.