

ACURA B2982: CLIMATE CONTROL UNIT LOST COMMUNICATION WITH EACH CONTROL MOTOR

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$75-\$200
Can I Still Drive?	:	Yes

What Does The Acura B2982 Code Mean?

BUS communication error is indicated.

Fault present in 1 or more of the following control motors: Driver's air mix control motor, the passenger's air mix control motor, the driver's cool vent control motor, the passenger's cool vent control motor, the mode control motor, the recirculation control motor, and the rear vent control motor.

What Are The Potential Causes Of The Acura B2982 Code?

- Loose wires or poor connections on the each control motor circuit
- Replace the control motor with a problem
- Faulty linkage or the door
- Faulty climate control unit

Reference Sources

[Acura B2982](#), DTCDECODE.