

## ACURA P1114: ECT SENSOR CIRCUIT LOW INPUT (INTERMITTENT)

### OVERVIEW

|                      |   |                         |
|----------------------|---|-------------------------|
| Severity             | : | <div>High</div>         |
| DIY Difficulty Level | : | <div>Intermediate</div> |
| Repair Cost          | : | \$50-\$200              |
| Can I Still Drive?   | : | Yes                     |

### What Does The Acura P1114 Code Mean?

Engine started, engine runtime 1 minute, and the PCM detected an unexpected low voltage of under 0.10v [Scan Tool read 302°F] on the ECT sensor circuit for 10 seconds over a 100 second period.

**Note:** For additional help with this code, view the Failure Re

### What Are The Potential Causes Of The Acura P1114 Code?

- ECT sensor signal circuit shorted to ground (intermittent fault)
- ECT sensor is damaged or has failed
- PCM has failed

### Reference Sources

[Acura P1114](#), DTCDECODE.