

ACURA P1115: ECT SENSOR CIRCUIT HIGH INPUT (INTERMITTENT)

OVERVIEW

Severity	:	High
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$50-\$200
Can I Still Drive?	:	Yes (Short-term only)

What Does The Acura P1115 Code Mean?

Engine started, engine runtime 1 minute, and the PCM detected an unexpected high voltage of over 4.90v [Scan Tool reads -38°F] on the ECT sensor circuit for 10 seconds over a 100 second period.

What Are The Potential Causes Of The Acura P1115 Code?

Below are some potential causes of this DTC:

- ECT sensor signal circuit is open (an intermittent fault)
- ECT sensor is damaged or has failed (an intermittent fault)
- PCM has failed

Reference Sources

[Acura P1115](#), DTCDECODE.