

ACURA P1133: HO2S-11 (BANK 1 SENSOR 1) INSUFFICIENT SWITCHING

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$100-\$200
Can I Still Drive?	:	Yes (Short-term only)

What Are The Potential Causes Of The Acura P1133 Code?

Below are some potential causes of this DTC:

- Air leaks after the MAF sensor, or in the EGR or PCV system
- Exhaust leaks before or near where the front HO2S is mounted
- Fuel control sensor is out of calibration (i. e. , ECT, IAT or MAP)
- Fuel delivery system supplying too much or too little

Reference Sources

[Acura P1133](#), DTCDECODE.