

## ACURA P1172: REAR AIR/FUEL RATIO (A/F) SENSOR (BANK 1, SENSOR 1) CIRCUIT OUT OF RANGE HIGH

### OVERVIEW

|                      |   |                                    |
|----------------------|---|------------------------------------|
| Severity             | : | <div><div>High</div></div>         |
| DIY Difficulty Level | : | <div><div>Intermediate</div></div> |
| Repair Cost          | : | \$100-\$300                        |
| Can I Still Drive?   | : | Yes                                |

### What Does The Acura P1172 Code Mean?

A malfunction is detected when the rear A/F sensor (bank 1, sensor 1) output voltage is 4.7 V or more. The execution time is continuous and the duration time is 7 seconds or more.

NOTE: Before you troubleshoot, record all freeze data and any on-board snapshot.

### What Are The Potential Causes Of The Acura P1172 Code?

- Poor connections or loose terminals at the A/F sensor (Sensor 1) and the PCM
- Faulty A/F sensor (Sensor 1)

### Reference Sources

[Acura P1172](#), DTCDECODE.