ΓHROT	TLE POSITION INSUFFICIEN
	OVERVIEW
:	Medium
:	Intermediate
:	\$200-\$600
:	Yes
	:

What Does The Acura P1243 Code Mean?

Engine running at road load, with at least one wide-open throttle event, and the PCM detected an insufficient throttle position value.

What Are The Potential Causes Of The Acura P1243 Code?

- Throttle valve is stuck, damaged or has failed
- TP sensor is damaged or has failed
- Throttle valve control motor is damaged or has failed

Reference Sources

Acura P1243, DTCDECODE.

