

What Does The Acura P1246 Code Mean?

Key on or engine running; and the PCM detected an unexpected voltage condition on the Accelerator Pedal Position Sensor 1 circuit.

What Are The Potential Causes Of The Acura P1246 Code?

- APP sensor 1 signal circuit is open
- APP sensor 1 signal circuit is shorted to ground
- APP sensor 1 signal circuit shorted to VREF or system power
- APP sensor is damaged or has failed
- PCM has failed

Reference Sources

Acura P1246, DTCDECODE.

