

## ACURA P1248: ACCELERATOR PEDAL POSITION SENSOR CORRELATION

### OVERVIEW

Severity	:	<div><div></div></div> High
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$100-\$300
Can I Still Drive?	:	Yes (Short-term only)

### What Does The Acura P1248 Code Mean?

Condition for setting the DTC: Key on or engine running; and the PCM detected the correlation between the Accelerator Pedal Position Sensor 1 and 2 signals were incorrect or not plausible.

### What Are The Potential Causes Of The Acura P1248 Code?

Below are some potential causes of this DTC:

- APP sensor is damaged or has failed
- APP sensor 2 is damaged or has failed
- Throttle plate or linkage is jammed or bent
- PCM has failed

### Reference Sources

[Acura P1248](#), DTCDECODE.