

ACURA P1359: CKP/TDC/CYP SENSOR CIRCUIT MALFUNCTION

OVERVIEW

Severity	:	High
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$200-\$400
Can I Still Drive?	:	Yes (Short-term only)

What Does The Acura P1359 Code Mean?

This code indicates that engine started, and the PCM detected an unexpected voltage condition on the CKP/TDC/CYP sensor circuit during the CCM test.

What Are The Potential Causes Of The Acura P1359 Code?

Below are some potential causes of this DTC:

- CKP/TDC/CYP signal circuit is open or shorted to ground
- CKP/TDC/CYP signal circuit is shorted to system power (B+)
- CKP/TDC/CYP pickup assembly or its pulse rotor is damaged
- CKP/TDC/CYP is damaged or has failed
- PCM has failed

Reference Sources

[Acura P1359](#), DTCDECODE.