

What Does The Acura P1386 Code Mean?

Engine running and the PCM detected an unexpected or intermittent interruption of the Camshaft Position 2 (CMP) sensor signal.

What Are The Potential Causes Of The Acura P1386 Code?

- CMP2 signal circuit is open or shorted to ground
- CMP2 signal circuit is shorted to VREF or system power
- CMP2 pickup unit or the CMP sensor is damaged or has failed
- PCM has failed

Reference Sources

Acura P1386, DTCDECODE.

