

ACURA P1457: EVAP SYSTEM LEAK DETECTED (CANISTER AREA)

OVERVIEW

Severity	:	<div><div></div></div> High
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$120-\$350
Can I Still Drive?	:	No

What Are The Potential Causes Of The Acura P1457 Code?

- EVAP canister is leaking, damaged or full of water
- EVAP canister purge line is loose, damaged or blocked
- EVAP two-way valve or ORVR vent shut valve is damaged
- EVAP fuel tank vapor control valve is damaged or has failed
- PCM has failed
- TSB

Reference Sources

- [2001 Engine Performance Acura Self-Diagnostics](#), MDX, 3.2CL & 3.2TL, pp.45-52.
- Americann Honda Motor Co, Inc., 2015, [Acura Technical Service Bulletin - Troubleshooting DTC P1456 and P1457](#).