

What Are The Potential Causes Of The Acura P1486 Code?

- ECT sensor is out of calibration
- Check for low coolant level or incorrect coolant mixture
- Cooling system component failure (thermostat stuck open)
- TSB 01-016 (9/10/01) contains a repair procedure for this code

Reference Sources

2001 Engine Performance Acura Self-Diagnostics, MDX, 3.2CL & 3.2TL, page 52.

