| ACURA P1618: SERIAL PERIPHERAL INTERFACE COMMUNICATION | | | |
|--|---|---------------|----------|
| | | OVERVIEW | |
| Severity | : | | High |
| DIY Difficulty Level | : | | Advanced |
| Repair Cost | : | \$1300-\$1700 | |
| Can I Still Drive? | : | No | |

What Does The Acura P1618 Code Mean?

Key on for 2 seconds, system voltage over 9v, and the PCM detected an internal program fault (the check sum of the data communications error) for 3 out of 6 seconds with no TCM resets during the test period of 2 seconds.

Note: For additional help with th

What Are The Potential Causes Of The Acura P1618 Code?

- Check the PCM calibration to verify it is the latest calibration
- Recalibrate the PCM as required
- PCM may need to be replaced and reprogrammed

Reference Sources

Acura P1618, DTCDECODE.

