ACURA P1671: A/T (TCM) FI DATA LINE NO SIGNAL		
	OVERVIEW	
:	Medium	
:	Intermediate	
:	\$75-\$200	
:	Yes	
	:	: Medium : Intermediate : \$75-\$200

What Does The Acura P1671 Code Mean?

Key on or engine running; and the PCM did not detect any signals on the A/T FI Data Line circuit during the CCM test.

What Are The Potential Causes Of The Acura P1671 Code?

- A/T FI data line is open
- A/T FI data line is shorted to sensor ground or chassis ground
- A/T FI data line is shorted to VREF or system power
- TCM or PCM has failed

Reference Sources

Acura P1671, DTCDECODE.