

ACURA P1672: A/T (TCM) FI DATA LINE CIRCUIT MALFUNCTION

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$75-\$200
Can I Still Drive?	:	Yes

What Does The Acura P1672 Code Mean?

Engine started, and the PCM detected an unexpected (intermittent) interruption of the TCM FI Data Line signal during the CCM test.

What Are The Potential Causes Of The Acura P1672 Code?

- A/T FI data line is open (intermittent fault)
- A/T FI data line is shorted to ground (intermittent fault)
- A/T FI data line is shorted to VREF or power (intermittent fault)
- TCM or PCM has failed

Reference Sources

[Acura P1672](#), DTCDECODE.