

ACURA P1710: A/T FIRST HOLD SWITCH CIRCUIT MALFUNCTION

OVERVIEW

Severity	:	<div><div>High</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$170-\$300
Can I Still Drive?	:	No

What Does The Acura P1710 Code Mean?

Key on or engine running; and the PCM detected an unexpected voltage condition on the First Hold switch circuit during the test.

What Are The Potential Causes Of The Acura P1710 Code?

- First hold witch signal circuit is open
- First hold switch is shorted to ground
- First hold switch ground circuit is open
- First hold switch is shorted to VREF or system power
- First hold switch is damaged or has failed
- TCM or PCM has failed

Reference Sources

[Acura P1710](#), DTCDECODE.