

## ACURA P1738: A/T 2ND PRESSURE SWITCH CIRCUIT MALFUNCTION

### OVERVIEW

Severity	:	<div><div>High</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$170-\$300
Can I Still Drive?	:	No

### What Does The Acura P1738 Code Mean?

Engine running in gear, and the PCM detected an unexpected voltage condition on the 2nd pressure switch circuit during the test.

### What Are The Potential Causes Of The Acura P1738 Code?

- A/T 2nd pressure switch signal circuit is open
- A/T 2nd pressure switch signal circuit is shorted to ground
- A/T 2nd pressure switch signal circuit shorted to system power
- A/T 2nd pressure switch is damaged or has failed
- TCM or PCM has failed

### Reference Sources

[Acura P1738](#), DTCDECODE.