

ACURA P1791: A/T VEHICLE SPEED SENSOR CIRCUIT MALFUNCTION

OVERVIEW

Severity	:	<div>High</div>
DIY Difficulty Level	:	<div>Intermediate</div>
Repair Cost	:	\$100-\$350
Can I Still Drive?	:	No

What Does The Acura P1791 Code Mean?

Vehicle driven for 15 seconds, and the PCM detected an unexpected voltage condition on the vehicle speed signal circuit to the TCM.

Note: The lockup clutch does not engage when this code is set.

Note: The D4 lamp on the dash will flash 4 times if this co

What Are The Potential Causes Of The Acura P1791 Code?

- VSS signal circuit to the TCM is open
- VSS signal circuit is shorted to ground
- VSS signal circuit to the TCM is shorted to VREF
- VSS connector is disconnected or damaged
- TCM or PCM has failed

Reference Sources

[Acura P1791](#), DTCDECODE.