

ACURA P1792: A/T ENGINE COOLANT TEMPERATURE SENSOR CIRCUIT MALFUNCTION

OVERVIEW

Severity	:	High
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$50-\$200
Can I Still Drive?	:	Yes

What Does The Acura P1792 Code Mean?

Key on or engine running; and the PCM detected an unexpected voltage condition on the ECT sensor signal circuit to the TCM.

Note: The lockup clutch does not engage when this code is set. Note: The D4 lamp on the dash will flash 10 times if this code is s

What Are The Potential Causes Of The Acura P1792 Code?

- ECT signal circuit to the TCM is open
- ECT signal circuit to the TCM is shorted to ground
- ECT signal circuit to the TCM is shorted to VREF
- ECT sensor connector is disconnected or damaged
- TCM or PCM has failed

Reference Sources

[Acura P1792](#), DTCDECODE.